





Sheave Wear Indicators

Sheaves should be checked for wear everytime you change a belt!



Normal Sheave (Uniform Angle)



Worn Sheave (Dished Out)


Indications of sheave wear include:

- Belts are turning over
- Belts wear out faster than normal
- Belts are “bottoming” out
- Belt dressing is used to quiet drive not enough tension or worn grooves)
- Belts appear to be “mismatched”

If wear is present, Martin offers replacement sheaves

- Instant availability QD and Taper Bushed
- The best MTO capability - cast iron, ductile and steel
- Expertise in personnel to assist your efforts
- Complimentary groove gauges available for customer inspection

AMS-KSEIndonesia Corp



PT. APINDO MITRA SELARAS

Serang Office :

Komp. Lebak Indah Griya Asri
Blok D4-D5 No.17 & No.05
Waringin Kuring - Kramatwatu
Serang, Banten
42161

Cilegon Office :

Jl. Raya Pondok Cilegon Indah
Ruko Cilegon City Square Blok I No.7
Kedaleman - Cibeer
Cilegon, Banten
42422

aris@kseindonesia.com - sales@kseindonesia.com - cso@kseindonesia.com
www.kseindonesia.com